



AHT Liftgates, LLC

309 Mogie Ln.

Acworth, Ga. 30102

(727) 452-0174

E-Mail: parts@ahtliftgates.com

Web: www.ahtliftgates.com

STEEL TROUBLESHOOTING GUIDE

PROBLEM	CAUSE	CORRECTION
MOTOR SOUNDS STRANGE	1) <i>Low hydraulic oil</i>	- Put platform on ground. Check oil level. Add new oil to within 1" from top of tank.
	2) <i>Shuttle Valve Defective</i>	- Remove shuttle valve, dismantle it and blow it out with air. Reassemble and reinstall. Be careful not to over tighten. If still not working replace.
	3) <i>Motor Defective</i>	- Replace motor