



AHT Liftgates, LLC
309 Mogie Ln.
Acworth, Ga. 30102
(727) 452-0174

E-Mail: parts@ahtliftgates.com
Web: www.ahtliftgates.com

STEEL TROUBLESHOOTING GUIDE

PROBLEM	CAUSE	CORRECTION
PLATFORM LOWERS WHILE OPENING	<i>1) Lift Valve C-30 is leaking</i>	-Clean or replace C-30 cartridge